



Contract No. 009359	Station Section 1	Mile/Line: I-90	C/S <div></div>
Staked by SURVEY	Date 8/5/2019	Work Started Date 8/5/2019	Work Completed Date <div></div>
Calculated by Scott Busby	Date 9/5/2019	Checked by E. Knudson	Inspector Scott Busby
		Date 9/10/2019	Date 9/5/19

ITEM NO. 17
Section 1 - I-90, MP 33.44 to MP 136.43
BEAM GUARDRAIL ANCHOR TYPE 10

Group Number 8

8/6/2019 - I-90

- Station MP 85.88 Main LT WB - Sheet 4 - Installed **One EA** Beam Guardrail Anchor Type 10
 - 12.5** LF
 - 3** wood posts

Group Number 11

8/6/2019 - I-90

- Station MP 109.45 Main LT EB - Sheet 11 - Installed **One EA** Beam Guardrail Anchor Type 10
 - 12.5** LF
 - 3** wood posts

Notes:

How Measured: Per Each - Checked in the field as installed

Item Num	Material Brand Name/Model Type	Manufacturer	Brand Name/Model Type	RAMS/QPL Ref. No.	Appr/Acc Code	Basis of Accept
017.01	Beam Guardrail Anchors	Trinity Highway Products, LLC		QPL-0003	2215	/ Manufacturer's Certificate of Compliance and Supporting Test Results
017.03	Beam Guardrail Wood Post and Blocks	Superior Wood Treating		QPL-0005	2550	/ Lumber Grading Stamp or Grading Certificate and Certificate of Treatment. (If Aquatic Envir. Std. Spec. 9-09.3 (1) Applies)

Item Num	Item Description	Grp	Date Work Complete	Unit	Quantity	Ledger Entry No.	Posted By Init.	Posted By Date	Checked By Init.	Checked By Date	Est. No.
0017	BEAM GUARDRAIL ANCHOR TYPE 10	8	9/5/2019	EAC H	1	295	EK	09/11/19			6
0017	BEAM GUARDRAIL ANCHOR TYPE 10	11	9/5/2019	EAC H	1	296	EK	09/11/19			6

Attachments



Things to do 82-2.xlsx
Microsoft Excel
Worksheet
409 KB

DOT Form IP 422-635ER EF
Revised 4/2009